

CivilFEM Class3 Error report

ERROR Number: 2016009

BUG Number: D-02023

First incorrect version: 2015

Corrected in: 2016 SP4

Description of Error:

Any change in bending reinforcement groups from copied cross section are not taken into account in bending checking/design




Keywords: Concrete ,Cross Section , Bending Reinforcement , Checking/Design

GUI Access:

Suggested User Action For Running on Uncorrected Version:

Once the cross section has been copied and modified, save and load the database file (*.xcf or *.cf).

Comments:

18/11/2016 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Corrected by Firmado por: José Luis Gómez	18/11/2016 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Reviewed by Firmado por: Luis Valdivia Montoro
18/11/2016 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Approval Firmado por: José M. Moreno	