

CivilFEM Class3 Error report

ERROR Number: SD2022003

BUG Number: CFM-22

First incorrect version: CivilFEM 2015 powered by Marc

Corrected in: CivilFEM 2022 SP2 powered by Marc

Description of Error:




Shear forces on concrete beams with shear effects could be wrong if exists other beams without shear effects activated.

Suggested User Action For Running on Uncorrected Version:

Activate or deactivate the shear effects checkbox for all the concrete beams.

Comments:

N/A

02/11/2022 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Corrected by Firmado por: Javier Carro	11/01/2023 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Reviewed by Firmado por: Alberto Mota
06/02/2023 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Approval Firmado por: Hugo González	