

CivilFEM Class3 Error report

ERROR NO: 2010-004

BUG NO: 2010032

First incorrect version: 11.0 Rev 4a

Corrected in: 11.0 Rev 4a SP6

Description of Error:

Axial forces may be incorrect in Solid 2 Shell tool in curved surfaces

Keywords:

Solid2Shell

GUI Access:

NONE

Suggested User Action For Running on Uncorrected Version:

Comments:

Author:

Date:

Signature:

Corrected by: Román Martín

22/06/2010

Reviewed by: Jose Luis Gómez

22/06/2010

Approval: Eduardo Salete

23/06/2010