

CivilFEM Class3 Error report

ERROR Number: 2020001

BUG Number: D-03582

First incorrect version: CivilFEM for ANSYS 12.0

Corrected in: CivilFEM 2020 for ANSYS

Description of Error:




Bending class of cross sections according EC3 could be wrongly calculated.

Suggested User Action For Running on Uncorrected Version:

N/A

Comments:

The error occurs when exists plates in pure traction.

08/07/2020 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Corrected by Firmado por: Javier Carro	08/07/2020 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Reviewed by Firmado por: Alberto Mota
08/07/2020 <div style="text-align: center;">  X </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Approval Firmado por: Hugo González	