

CivilFEM Class3 Error report

ERROR Number: SD2016008

BUG Number: D-01970

First incorrect version: CivilFEM 2015

Corrected in: CivilFEM 2016 SP3

Description of Error:

Concrete time-dependent properties are not evaluated correctly in transient analysis. Elastic modulus of concrete for 28 days is always used regardless of the age of material.

Keywords:




GUI Access:

Transient Analysis: [Load case]->Calendar time /[Concrete Material]-> Activation time

Suggested User Action For Running on Uncorrected Version:

Comments:

This error occurs in transient analysis using concrete material with age different from 28 days.

14/09/2016	15/09/2016
 X _____	 X _____
Corrected by Firmado por: Javier Carro	Reviewed by Firmado por: José Luis Gómez
15/09/2016	
 X _____	
Approval Firmado por: José M. Moreno	