

## CivilFEM Class3 Error report

**ERROR Number:** SD2024002

**BUG Number:** CFM-202

**First incorrect version:** CivilFEM 2017 powered by Marc

**Corrected in:** CivilFEM 2024 powered by Marc

**Description of Error:**




In some cases there is an error while transforming the solid stress tensor to the solid section coordinate system.

**Suggested User Action For Running on Uncorrected Version:**

Use the same coordinate system for the solid structural element and the solid section

**Comments:**

N/A

23/07/2024  <div style="text-align: center;">   <span style="font-size: 2em; font-weight: bold;">X</span> </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Corrected by Firmado por: Javier Carro	30/07/2024  <div style="text-align: center;">   <span style="font-size: 2em; font-weight: bold;">X</span> </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Reviewed by Firmado por: Israel Cabañas
06/11/2024  <div style="text-align: center;">   <span style="font-size: 2em; font-weight: bold;">X</span> </div> <hr style="border: 1px solid black; margin: 5px 0;"/> Approval Firmado por: Hugo González	