

---

## CIVILFEM Class3 Error Report

**ERROR NO: 2007-002**

**Keywords: Shell, Design, Concrete**

**Description of the Error:** Detected in v.11 rev.3  
Error via CivilFEM window menu when input "Stress" value in shell MUD design. Argument is saved in wrong position (fifth instead seventh position)

**Comments:**

**GUI Access: Main Menu > Civil Postprocessor > Code Checking>"Code"> DESIGN BY CODE: Shells>MUD Method**

**First Incorrect Version:**

**Corrected Version:**

**Workaround provided:** Use design by MUD Method via command line, i.e.:  
**~DIMCON,SHELL,MUD,,,,,250000000**

**Author / Signature: Ronald Siat Date: 18/12/2007**

**Reviewed by QA: Román Martín Date: 18/1/2008**

**Approval: Eduardo Salete Date: 21/1/2008**